Site HOTO Report — DHK_X2119

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 07-Nov-2026 02:33 BD time

36%	0/0	3	3	21
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Inspected By, DG Present Status, Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X2119	ZONE	Sylhet
HOTO DATE	2026-09-06	DISTRICT	Narsingdi
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Md. Mahabur Rahman
HANDOVER PHONE	01958313020	TAKEOVER PHONE	01615220637
INSPECTED BY	Not Filled	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	67	PRESENT RH	2429
FUEL (NO WATER)	— L	FUEL (TOTAL)	12.7 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	Not Filled	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	PO33WKGH0055
BATTERY AH	100	ENGINE SERIAL	0240920/045
ATS BRAND	Tempest	ATS MODE	Auto
RH METER TYPE	Manual meter	LAST SERVICE DATE	2026-06-28
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	**CONNECTED FUEL TANKS**	—
FAULTY/DISCONNECTED DG	—	**FAULTY/DISCONNECTED TANKS**	—

SNAGS FOUND (3)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-089	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-090	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-091	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	


DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	Room Light Fault; Faulty fuel tank (2pc available); 1pc DG canopy open (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X2119_EXTRA_010.jpg) on 2026-09-09.

SITE PHOTOS

No Photo
Not Filled Site / Nameplate

No Photo
Not Filled DG RH / Meter




Fuel Gauge


Additional


Additional


Additional



Additional


Additional

Md. Kabir Hossen	**Md. Mahabur Rahman**	
Handed Over By · —	Taken Over By · —	BL Concern · Name / Signature
01958313020	01615220637	
Date: _____	Date: _____	Date: _____

APPENDIX — PHOTO EVIDENCE (21)

Full-size reference photos for DHK_X2119, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)




Photo 1 — Fuel Gauge

SNAG EVIDENCE PHOTOS (3)



Photo 2 — S-089 — (from HOTO Telegram group photo -- needs review)



Photo 3 — S-090 — (from HOTO Telegram group photo -- needs review)



Photo 4 — S-091 — (from HOTO Telegram group photo -- needs review)

ADDITIONAL PHOTOS (17)



Photo 5 — Additional Photos 1



Photo 6 — Additional Photos 2



Photo 7 — Additional Photos 3




Photo 8 — Additional Photos 4



Photo 9 — Additional Photos 5



Photo 10 — Additional Photos 6



Photo 11 — Additional Photos 7




Photo 12 — Additional Photos 8



Photo 13 — Additional Photos 9




Photo 14 — Additional Photos 10




Photo 15 — Additional Photos 11



Photo 16 — Additional Photos 12



Photo 17 — Additional Photos 13



Photo 18 — Additional Photos 14



Photo 19 — Additional Photos 15



Photo 20 — Additional Photos 16



Photo 21 — Additional Photos 17