# Site HOTO Report — DHK_X1171

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:26 BD time

| 45% | 0/0 | 1 | 1 | 16 |
|---|---|---|---|---|
| FORM COMPLETION | CHECKLIST OK | OPEN SNAGS | TOTAL SNAGS | PHOTOS ATTACHED |

**Incomplete:** the following expected fields were left blank in this submission — Inspected By, Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

## SITE & HANDOVER DETAILS

| | | | |
|---|---|---|---|
| SITE CODE | DHK_X1171 | ZONE | Sylhet |
| HOTO DATE | 2026-09-06 | DISTRICT | Narsingdi |
| HANDOVER ORG | — | TAKEOVER ORG | — |
| HANDOVER PERSON | Md. Kabir Hossen | TAKEOVER PERSON | Md. Malabuz Rahman |
| HANDOVER PHONE | 01958313020 | TAKEOVER PHONE | 01615220637 |
| INSPECTED BY | Not Filled | SECURITY GUARD | — |
| ACCESS KEY HANDED OVER | — | SITE TYPE | Not Filled |
| BTS TYPE | Not Filled | | |
| SHARED WITH OPERATOR | Not Filled | SHARED OPERATOR NAME | — |

## GENERATOR INFORMATION

| | | | |
|---|---|---|---|
| DG BRAND | Tempest | GENSET ASSET NO. | — |
| CAPACITY (KVA) | 20 | TYPE | — |
| FUEL TANK CAPACITY | 2000 | PRESENT RH | 3784 |
| FUEL (NO WATER) | — L | FUEL (TOTAL) | 225.6 L |
| WATER AMOUNT | — L | FUEL AMOUNT (WORD) | — |
| DG SITE TYPE | — | DG LOCKED AFTER FUELING | — |
| DG PRESENT STATUS | OK | GENSET ON ALARM | — |
| BATTERY BRAND | Spark | BATTERY SERIAL | — |
| BATTERY AH | 100 | ENGINE SERIAL | — |
| ATS BRAND | — | ATS MODE | Auto |
| RH METER TYPE | Digital from controller | LAST SERVICE DATE | 2026-07-27 |
| KEY TYPE | — | KEY STATUS — BTS | — |
| KEY STATUS — DG ROOM | — | | |

| | | | |
|---|---|---|---|
| **ACTIVE DG** | — | **CONNECTED FUEL TANKS** | — |
| **FAULTY/DISCONNECTED DG** | — | **FAULTY/DISCONNECTED TANKS** | — |

## SNAGS FOUND (1)

| SNAG # | SYSTEM | CATEGORY | COMPONENT | STATUS | OBSERVATIONS | ACTION | PHOTO |
|---|---|---|---|---|---|---|---|
| S-076 | General | — | (from HOTO Telegram group photo -- needs review) | Faulty | Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation. | Open |  |

## DEFICIENCIES & SAFETY REMARKS


| | |
|---|---|
| **DG MAJOR DEFICIENCIES** | Canopy open; Room light (from paper handover checklist) |
| **SAFETY REMARKS** | — |
| **GENERAL REMARKS** | Technical fields backfilled from paper handover checklist photo (DHK_X1171_EXTRA_001.jpg) on 2026-09-09. Engine serial, battery serial no, and ATS brand were illegible on the photo -- left blank, please fill in from the physical form if available. |

## SITE PHOTOS

Not Filled Site / Nameplate


DG RH / Meter

Not Filled Fuel Gauge


Additional


Additional


Additional


Additional


Additional


Additional

**Md. Kabir Hossen**
Handed Over By · —
01958313020

Date: _____

**Md. Malabuz Rahman**
Taken Over By · —
01615220637

Date: _____

BL Concern · Name / Signature

Date: _____

## APPENDIX — PHOTO EVIDENCE (16)

Full-size reference photos for DHK_X1171, grouped by type and numbered for cross-reference against the tables above.

### REQUIRED SITE PHOTOS (1)




**Photo 1 — DG RH / Meter**

### SNAG EVIDENCE PHOTOS (1)




**Photo 2 — S-076 — (from HOTO Telegram group photo -- needs review)**

## ADDITIONAL PHOTOS (14)





**Photo 3 — Additional Photos 1**




**Photo 4 — Additional Photos 2**




**Photo 5 — Additional Photos 3**




**Photo 6 — Additional Photos 4**




**Photo 7 — Additional Photos 5**




**Photo 8 — Additional Photos 6**




**Photo 9 — Additional Photos 7**




**Photo 10 — Additional Photos 8**




**Photo 11 — Additional Photos 9**




**Photo 12 — Additional Photos 10**




**Photo 13 — Additional Photos 11**




**Photo 14 — Additional Photos 12**




**Photo 15 — Additional Photos 13**




**Photo 16 — Additional Photos 14**