Site HOTO Report — DHK_X1171

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 08:09 BD time

45%	0/0	1	1	16
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Inspected By, Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X1171	ZONE	Sylhet
HOTO DATE	2026-09-06	DISTRICT	Narsingdi
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Md. Malabuz Rahman
HANDOVER PHONE	01958313020	TAKEOVER PHONE	01615220637
INSPECTED BY	Not Filled	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	3784
FUEL (NO WATER)	— L	FUEL (TOTAL)	225.6 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Spark	BATTERY SERIAL	—
BATTERY AH	100	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-07-27
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	**CONNECTED FUEL TANKS**	—
FAULTY/DISCONNECTED DG	—	**FAULTY/DISCONNECTED TANKS**	—

SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-076	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS


DG MAJOR DEFICIENCIES	Canopy open; Room light (from paper handover checklist)
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X1171_EXTRA_001.jpg) on 2026-09-09. Engine serial, battery serial no, and ATS brand were illegible on the photo -- left blank, please fill in from the physical form if available.

SITE PHOTOS

Not Filled Site / Nameplate


DG RH / Meter

Not Filled Fuel Gauge


Additional


Additional


Additional


Additional


Additional


Additional

Md. Kabir Hossen
Handed Over By · —
01958313020

Date: _____

Md. Malabuz Rahman
Taken Over By · —
01615220637

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (16)

Full-size reference photos for DHK_X1171, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)



Photo 1 — DG RH / Meter

SNAG EVIDENCE PHOTOS (1)



Photo 2 — S-076 — (from HOTO Telegram group photo -- needs review)

ADDITIONAL PHOTOS (14)




Photo 3 — Additional Photos 1



Photo 4 — Additional Photos 2



Photo 5 — Additional Photos 3



Photo 6 — Additional Photos 4



Photo 7 — Additional Photos 5



Photo 8 — Additional Photos 6



Photo 9 — Additional Photos 7



Photo 10 — Additional Photos 8



Photo 11 — Additional Photos 9



Photo 12 — Additional Photos 10



Photo 13 — Additional Photos 11



Photo 14 — Additional Photos 12



Photo 15 — Additional Photos 13



Photo 16 — Additional Photos 14