Site HOTO Report — SYL_X0191

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:56 BD time

100%	14/15	3	3	46
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0191	ZONE	Sylhet
HOTO DATE	2026-09-05	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Anwae	TAKEOVER PERSON	Md. Ismail Hossain
HANDOVER PHONE	01734713807	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	No
ACCESS KEY HANDED OVER	Yes	SITE TYPE	GFT
BTS TYPE	Indoor		
SHARED WITH OPERATOR	No	SHARED OPERATOR NAME	N/A

GENERATOR INFORMATION

DG BRAND	FG Wilson	GENSET ASSET NO.	N/A
CAPACITY (KVA)	22	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	15796.7
FUEL (NO WATER)	241 L	FUEL (TOTAL)	241 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	Two Hundred Forty One Liters
DG SITE TYPE	Remote	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Lucas	BATTERY SERIAL	4362597
BATTERY AH	80	ENGINE SERIAL	HP511090U981933P
ATS BRAND	Genthe	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-04-30
KEY TYPE	Local Key	KEY STATUS — BTS	Local
KEY STATUS — DG ROOM	Local		
ACTIVE DG	1	CONNECTED FUEL TANKS	1

FAULTY/DISCONNECTED DG	0	FAULTY/DISCONNECTED TANKS	0

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	45
Frequency (Hz)	51.2	Phase	3 Phase
Output	393	Engine Brand	Perkings
Voltage L1-L2	391	Voltage L2-L3	393
Voltage L3-L1	393	Voltage L1-N	227
Voltage L2-N	227	Voltage L3-N	227
Current Line 1	15	Current Line 2	15
Current Line 3	15	N-G	2.23
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	NOK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		

SNAGS FOUND (3)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-060	DG	DG - Other	Lube oil level is low	Faulty	—	Open	
S-061	DG	DG - Other	MC 1 pole faulty	Faulty	—	Open	
S-062	DG	DG - Other	Need Overhaling	Faulty	—	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	Lub oil shortage; engine overhauling issue; 1 pole of PMC/EPMC faulty
SAFETY REMARKS	—

GENERAL REMARKS	PDF checklist notes: Site ID on form reads 'SYL-X0191' matching filename. Handing Over Vendor's participant name/signature/contact row was left BLANK - no handover_person/handover_org/handover_phone recorded on this form. DG last servicing date recorded as 30-4-26 (2026-04-30). This site likely already has a submitted (non-placeholder) visit in the DB per task context; use these values only to fill gaps.

SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge



Additional



Additional




Additional



Additional



Additional



Additional



Additional

Md. Anwae
Handed Over By · Dhaly Infratech
01734713807

Date: _____

Md. Ismail Hossain
Taken Over By · Alliance Computers Limited
01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (46)

Full-size reference photos for SYL_X0191, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (3)



Photo 4 — S-060 — Lube oil level is low




Photo 5 — S-061 — MC 1 pole faulty



Photo 6 — S-062 — Need Overhaling

ADDITIONAL PHOTOS (40)



Photo 7 — Additional Photos 1



Photo 8 — Additional Photos 2



Photo 9 — Additional Photos 3




Photo 10 — Additional Photos 4



Photo 11 — Additional Photos 5




Photo 12 — Additional Photos 6




Photo 13 — Additional Photos 7




Photo 14 — Additional Photos 8




Photo 15 — Additional Photos 9




Photo 16 — Additional Photos 10




Photo 17 — Additional Photos 11




Photo 18 — Additional Photos 12




Photo 19 — Additional Photos 13



Photo 20 — Additional Photos 14



Photo 21 — Additional Photos 15



Photo 22 — Additional Photos 16



Photo 23 — Additional Photos 17




Photo 24 — Additional Photos 18




Photo 25 — Additional Photos 19




Photo 26 — Additional Photos 20



Photo 27 — Additional Photos 21




Photo 28 — Additional Photos 22



Photo 29 — Additional Photos 23




Photo 30 — Additional Photos 24



Photo 31 — Additional Photos 25




Photo 32 — Additional Photos 26



Photo 33 — Additional Photos 27



Photo 34 — Additional Photos 28



Photo 35 — Additional Photos 29




Photo 36 — Additional Photos 30



Photo 37 — Additional Photos 31



Photo 38 — Additional Photos 32



Photo 39 — Additional Photos 33



Photo 40 — Additional Photos 34



Photo 41 — Additional Photos 35



Photo 42 — Additional Photos 36




Photo 43 — Additional Photos 37



Photo 44 — Additional Photos 38



Photo 45 — Additional Photos 39



Photo 46 — Additional Photos 40