Site HOTO Report — SYL_X0405

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:52 BD time

55%	0/0	1	1	42
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0405	ZONE	Sylhet
HOTO DATE	2026-09-07	DISTRICT	Sylhet
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Ali Bahar	TAKEOVER PERSON	Md. Hemayetul Islam
HANDOVER PHONE	01728700949	TAKEOVER PHONE	01847426813
INSPECTED BY	Ali Bahar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Pramac	GENSET ASSET NO.	—
CAPACITY (KVA)	30	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	732
FUEL (NO WATER)	— L	FUEL (TOTAL)	125 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Lucas	BATTERY SERIAL	44539010
BATTERY AH	—	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	—
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	**CONNECTED FUEL TANKS**	—
FAULTY/DISCONNECTED DG	—	**FAULTY/DISCONNECTED TANKS**	—

SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-122	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG fuel pipe need to change; DG Radiator servicing needed; DG condition very poor; 1 phase missing (R-E-B); DG lube oil topped up 5 liter to keep site DG running (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from a paper handover checklist photo that was misfiled under SYL_X0218's Extra photos (SYL_X0218_EXTRA_051.jpg) -- the document's own printed Site ID field reads SYL-X405. Photo has been relocated to this visit. IMPORTANT: the Handover Status checkbox on the paper form appears marked "Not Completed", and remarks note "DG condition very poor" -- please verify with the field team before treating this handover as finalized. Backfilled 2026-09-09.


SITE PHOTOS


No Photo
Not Filled
Site / Nameplate



DG RH / Meter


No Photo
Not Filled
Fuel Gauge


Handover Checklist Document


Additional


Additional


Additional


Additional


Addit

Ali Bahar
Handed Over By · —
01728700949
Date: _____

Md. Hemayetul Islam
Taken Over By · —
01847426813
Date: _____

BL Concern · Name / Signature
Date: _____

APPENDIX — PHOTO EVIDENCE (42)

Full-size reference photos for SYL_X0405, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)



Photo 1 — DG RH / Meter

SNAG EVIDENCE PHOTOS (1)



Photo 2 — S-122 — (from HOTO Telegram group photo -- needs review)

HANDOVER CHECKLIST DOCUMENT (1)




Photo 3 — Handover Checklist Document 1

ADDITIONAL PHOTOS (39)




Photo 4 — Additional Photos 1



Photo 5 — Additional Photos 2




Photo 6 — Additional Photos 3



Photo 7 — Additional Photos 4




Photo 8 — Additional Photos 5




Photo 9 — Additional Photos 6




Photo 10 — Additional Photos 7



Photo 11 — Additional Photos 8



Photo 12 — Additional Photos 9



Photo 13 — Additional Photos 10




Photo 14 — Additional Photos 11




Photo 15 — Additional Photos 12




Photo 16 — Additional Photos 13



Photo 17 — Additional Photos 14




Photo 18 — Additional Photos 15



Photo 19 — Additional Photos 16



Photo 20 — Additional Photos 17



Photo 21 — Additional Photos 18



Photo 22 — Additional Photos 19



Photo 23 — Additional Photos 20



Photo 24 — Additional Photos 21



Photo 25 — Additional Photos 22




Photo 26 — Additional Photos 23



Photo 27 — Additional Photos 24



Photo 28 — Additional Photos 25



Photo 29 — Additional Photos 26



Photo 30 — Additional Photos 27




Photo 31 — Additional Photos 28



Photo 32 — Additional Photos 29



Photo 33 — Additional Photos 30



Photo 34 — Additional Photos 31



Photo 35 — Additional Photos 32



Photo 36 — Additional Photos 33



Photo 37 — Additional Photos 34



Photo 38 — Additional Photos 35



Photo 39 — Additional Photos 36



Photo 40 — Additional Photos 37




Photo 41 — Additional Photos 38




Photo 42 — Additional Photos 39