Site HOTO Report — SYL_X0426

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:40 BD time

45%	0/0	1	1	30
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0426	ZONE	Sylhet
HOTO DATE	2026-09-06	DISTRICT	Sylhet
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Ali Bahar	TAKEOVER PERSON	Md. Hemayetul Islam
HANDOVER PHONE	01728760949	TAKEOVER PHONE	01847426813
INSPECTED BY	Ali Bahar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	2277
FUEL (NO WATER)	— L	FUEL (TOTAL)	350 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	P033X1EB0033
BATTERY AH	100	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	2026-06-22
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	**CONNECTED FUEL TANKS**	—
FAULTY/DISCONNECTED DG	—	**FAULTY/DISCONNECTED TANKS**	—

SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-124	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS


DG MAJOR DEFICIENCIES	Need to DG Radiator servicing; DG Battery water low (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from a paper handover checklist photo that was misfiled under SYL_X0204's Extra photos (SYL_X0204_EXTRA_045.jpg) -- the document's own printed Site ID field reads SYL-X0426. Photo has been relocated to this visit. IMPORTANT: the Handover Status checkbox on the paper form appears marked "Not Completed", not "Completed" -- please verify with the field team before treating this handover as finalized. Backfilled 2026-09-09.

SITE PHOTOS

No Photo
Not Filled Site / Nameplate


No Photo
Not Filled DG RH / Meter

No Photo
Not Filled Fuel Gauge



Handover Checklist Document


Additional


Additional


Additional


Additional


Additional


Add

Ali Bahar
Handed Over By · —
01728760949

Date: _____

Md. Hemayetul Islam
Taken Over By · —
01847426813

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (30)

Full-size reference photos for SYL_X0426, grouped by type and numbered for cross-reference against the tables above.

SNAG EVIDENCE PHOTOS (1)



Photo 1 — S-124 — (from HOTO Telegram group photo -- needs review)

HANDOVER CHECKLIST DOCUMENT (1)




Photo 2 — Handover Checklist Document 1

ADDITIONAL PHOTOS (28)



Photo 3 — Additional Photos 1



Photo 4 — Additional Photos 2




Photo 5 — Additional Photos 3




Photo 6 — Additional Photos 4




Photo 7 — Additional Photos 5




Photo 8 — Additional Photos 6



Photo 9 — Additional Photos 7



Photo 10 — Additional Photos 8



Photo 11 — Additional Photos 9



Photo 12 — Additional Photos 10



Photo 13 — Additional Photos 11



Photo 14 — Additional Photos 12



Photo 15 — Additional Photos 13



Photo 16 — Additional Photos 14



Photo 17 — Additional Photos 15



Photo 18 — Additional Photos 16



Photo 19 — Additional Photos 17



Photo 20 — Additional Photos 18



Photo 21 — Additional Photos 19



Photo 22 — Additional Photos 20



Photo 23 — Additional Photos 21



Photo 24 — Additional Photos 22



Photo 25 — Additional Photos 23



Photo 26 — Additional Photos 24



Photo 27 — Additional Photos 25




Photo 28 — Additional Photos 26



Photo 29 — Additional Photos 27




Photo 30 — Additional Photos 28