Site HOTO Report — SYL_X0077

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:59 BD time

100%	20/20	0	0	33
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0077	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Moulavibazar
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Omar Faruk	TAKEOVER PERSON	Sourav sarkar
HANDOVER PHONE	01406394566	TAKEOVER PHONE	0184742670
INSPECTED BY	sourov sarkar	SECURITY GUARD	Yes
ACCESS KEY HANDED OVER	—	SITE TYPE	GFT
BTS TYPE	Indoor		
SHARED WITH OPERATOR	No	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Visa	GENSET ASSET NO.	No
CAPACITY (KVA)	30	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	629.2
FUEL (NO WATER)	— L	FUEL (TOTAL)	327 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	Three Hundred Twenty Seven Liters
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	PO33WJBK0524
BATTERY AH	100	ENGINE SERIAL	DJ51279
ATS BRAND	Bangla	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-06-28
KEY TYPE	Master Key - Abloy	KEY STATUS — BTS	Solex
KEY STATUS — DG ROOM	Local		
ACTIVE DG	1	CONNECTED FUEL TANKS	1

FAULTY/DISCONNECTED DG	—	**FAULTY/DISCONNECTED TANKS**	—

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Phase	3 Phase
Voltage L1-L2	390	Voltage L2-L3	400
Voltage L3-L1	395	Voltage L1-N	200
Voltage L2-N	210	Voltage L3-N	220
Current Line 1	8	Current Line 2	8
Current Line 3	9	Engine Brand	Perkn
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	OK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK	Mains Fail Alarm	OK
DC Low Alarm	OK	Door Open Alarm	OK
DG Run Alarm	OK	DG Failure Alarm	OK

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG Fuel pipe hard need to change Need to DG Radiator servicing DG Room light faulty Need to Fuel tank locking system
SAFETY REMARKS	—
GENERAL REMARKS	—

SITE PHOTOS




Site / Nameplate



DG RH / Meter



Fuel Gauge

 Additional	 Additional	 Additional	 Additional	 Add

Omar Faruk
Handed Over By · Dhaly Infratech
01406394566

Date: _____

Sourav sarkar
Taken Over By · Alliance Computers Limited
0184742670

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (33)

Full-size reference photos for SYL_X0077, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

ADDITIONAL PHOTOS (30)



Photo 4 — Additional Photos 1



Photo 5 — Additional Photos 2



Photo 6 — Additional Photos 3



Photo 7 — Additional Photos 4



Photo 8 — Additional Photos 5




Photo 9 — Additional Photos 6




Photo 10 — Additional Photos 7



Photo 11 — Additional Photos 8



Photo 12 — Additional Photos 9



Photo 13 — Additional Photos 10



Photo 14 — Additional Photos 11



Photo 15 — Additional Photos 12



Photo 16 — Additional Photos 13




Photo 17 — Additional Photos 14




Photo 18 — Additional Photos 15



Photo 19 — Additional Photos 16




Photo 20 — Additional Photos 17



Photo 21 — Additional Photos 18




Photo 22 — Additional Photos 19



Photo 23 — Additional Photos 20



Photo 24 — Additional Photos 21



Photo 25 — Additional Photos 22



Photo 26 — Additional Photos 23



Photo 27 — Additional Photos 24



Photo 28 — Additional Photos 25




Photo 29 — Additional Photos 26



Photo 30 — Additional Photos 27



Photo 31 — Additional Photos 28



Photo 32 — Additional Photos 29



Photo 33 — Additional Photos 30