Site HOTO Report — SYL_X0089

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:44 BD time

100%	14/15	1	1	38
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0089	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Anwar	TAKEOVER PERSON	Md. Ismail Hossain
HANDOVER PHONE	01734713807	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	Yes
ACCESS KEY HANDED OVER	Yes	SITE TYPE	GFT
BTS TYPE	Outdoor		
SHARED WITH OPERATOR	No	SHARED OPERATOR NAME	N/A

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	N/A
CAPACITY (KVA)	20	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	2241
FUEL (NO WATER)	104 L	FUEL (TOTAL)	104 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	One hundred four litter
DG SITE TYPE	Remote	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	P033XEBD0616
BATTERY AH	100	ENGINE SERIAL	GN66044U
ATS BRAND	Local	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-04-30
KEY TYPE	Local Key	KEY STATUS — BTS	Local
KEY STATUS — DG ROOM	Local		
ACTIVE DG	1	CONNECTED FUEL TANKS	1
FAULTY/DISCONNECTED DG	0	FAULTY/DISCONNECTED TANKS	0

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	34
Frequency (Hz)	51	Phase	3 Phase
Output	410	Engine Brand	Parkings
Voltage L1-L2	410	Voltage L2-L3	410
Voltage L3-L1	409	Voltage L1-N	235
Voltage L2-N	235	Voltage L3-N	234
Current Line 1	11	Current Line 2	12
Current Line 3	11	N-G	0.047
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	NOK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		

SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-008	DG	DG - Other	Over Run	Faulty	—	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	Need to servicing
SAFETY REMARKS	Need to servicing
GENERAL REMARKS	Need to servicing | PDF checklist notes: Working/Faulty checkbox for 'Generator status during handover' was not visible/marked in the crop (row appears blank, unlike other sites where 'Working' is ticked). Lub Oil Status is NOK but the Remarks/Snags Summary section was left blank - no detail on the oil issue. Neither Completed nor Not Completed box in Handover Status was checked. Engine serial number partially cut off/ambiguous ('GN6604U B'). DG last servicing date noted as 30/4/2026.

SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge



Additional




Additional




Additional



Additional



Additional



Additio

Md. Anwar
Handed Over By · Dhaly Infratech
01734713807

Date: _____

Md. Ismail Hossain
Taken Over By · Alliance Computers Limited
01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (38)

Full-size reference photos for SYL_X0089, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate




Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (1)



Photo 4 — S-008 — Over Run

ADDITIONAL PHOTOS (34)



Photo 5 — Additional Photos 1



Photo 6 — Additional Photos 2



Photo 7 — Additional Photos 3



Photo 8 — Additional Photos 4



Photo 9 — Additional Photos 5



Photo 10 — Additional Photos 6




Photo 11 — Additional Photos 7



Photo 12 — Additional Photos 8



Photo 13 — Additional Photos 9




Photo 14 — Additional Photos 10




Photo 15 — Additional Photos 11




Photo 16 — Additional Photos 12




Photo 17 — Additional Photos 13



Photo 18 — Additional Photos 14



Photo 19 — Additional Photos 15




Photo 20 — Additional Photos 16




Photo 21 — Additional Photos 17




Photo 22 — Additional Photos 18



Photo 23 — Additional Photos 19



Photo 24 — Additional Photos 20



Photo 25 — Additional Photos 21



Photo 26 — Additional Photos 22



Photo 27 — Additional Photos 23



Photo 28 — Additional Photos 24



Photo 29 — Additional Photos 25




Photo 30 — Additional Photos 26



Photo 31 — Additional Photos 27



Photo 32 — Additional Photos 28



Photo 33 — Additional Photos 29




Photo 34 — Additional Photos 30




Photo 35 — Additional Photos 31



Photo 36 — Additional Photos 32



Photo 37 — Additional Photos 33



Photo 38 — Additional Photos 34