Site HOTO Report — SYL_X0103

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:43 BD time

73%	15/15	4	4	35
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0103	ZONE	Sylhet
HOTO DATE	2026-09-02	DISTRICT	Moulavibazar
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Sayed	TAKEOVER PERSON	Sourav sarkar
HANDOVER PHONE	017163327	TAKEOVER PHONE	01847426870
INSPECTED BY	sourov sarkar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Ghadder	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	7873
FUEL (NO WATER)	354 L	FUEL (TOTAL)	354 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	Three Hundred Fifty Four Liters
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Spark	BATTERY SERIAL	3J06AL11015303
BATTERY AH	80	ENGINE SERIAL	N8431496N52001
ATS BRAND	Local	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-06-18
KEY TYPE	Master Key - Abloy	KEY STATUS — BTS	Abloy
KEY STATUS — DG ROOM	Abloy		

ACTIVE DG	1	**CONNECTED FUEL TANKS**	1
FAULTY/DISCONNECTED DG	0	**FAULTY/DISCONNECTED TANKS**	0

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Engine Brand	Perkins	Controller Status	OK
Black Smoke Status	OK	DG Battery Charger	OK
ATS Physical & Functional Status	OK	DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK
Fuel Preserved at Safe & Appropriate Location	OK	Exhaust Fan / Ventilation Sufficient When Running	OK
Sufficient Water in Radiator & Battery	OK	DG Radiator Condition	OK
DG Battery Condition	OK	DG Runs in Both Auto & Manual Mode	OK
GENSET ON Alarm Functioning Properly	OK	Lub Oil Status (Level & Colour)	OK
DG RH Meter Working Properly	OK	No Parts Missing (if missing, note in snags below)	OK

SNAGS FOUND (4)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-003	DG	DG - Other	Fuel pipe hard	Faulty	—	Open	—
S-004	DG	DG - Other	Need to fuel tank lock system,& pipe protection	Faulty	—	Open	
S-125	DG - Controller/Electronics	—	Temperature Sensor (□□□□□□□□□ □□□□□□)	Faulty	Hi Temp and Smoke sensor NOK (from paper handover checklist).	Open	—
S-126	Structural/Civil Damage	—	ATS Door (ATS □□□□)	Faulty	ATS Door Lock Broken (from paper handover checklist).	Open	—

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	Hi temp sensor NOK
SAFETY REMARKS	—
GENERAL REMARKS	—


SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge



Additional



Additional



Additional



Additional



Addi

Sayed
Handed Over By · Dhaly Infratech
017163327

Date: _____

Sourav sarkar
Taken Over By · Alliance Computers Limited
01847426870

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (35)

Full-size reference photos for SYL_X0103, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (1)



Photo 4 — S-004 — Need to fuel tank lock system,& pipe protection

ADDITIONAL PHOTOS (31)



Photo 5 — Additional Photos 1



Photo 6 — Additional Photos 2



Photo 7 — Additional Photos 3



Photo 8 — Additional Photos 4




Photo 9 — Additional Photos 5



Photo 10 — Additional Photos 6



Photo 11 — Additional Photos 7



Photo 12 — Additional Photos 8



Photo 13 — Additional Photos 9



Photo 14 — Additional Photos 10



Photo 15 — Additional Photos 11



Photo 16 — Additional Photos 12



Photo 17 — Additional Photos 13



Photo 18 — Additional Photos 14



Photo 19 — Additional Photos 15



Photo 20 — Additional Photos 16



Photo 21 — Additional Photos 17



Photo 22 — Additional Photos 18



Photo 23 — Additional Photos 19



Photo 24 — Additional Photos 20



Photo 25 — Additional Photos 21



Photo 26 — Additional Photos 22



Photo 27 — Additional Photos 23



Photo 28 — Additional Photos 24



Photo 29 — Additional Photos 25




Photo 30 — Additional Photos 26



Photo 31 — Additional Photos 27



Photo 32 — Additional Photos 28



Photo 33 — Additional Photos 29



Photo 34 — Additional Photos 30



Photo 35 — Additional Photos 31