Site HOTO Report — SYL_X0086

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:26 BD time

100%	14/15	2	2	39
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0086	ZONE	Sylhet
HOTO DATE	2026-09-02	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Eidris Ali	TAKEOVER PERSON	Md. Ismail Hossain
HANDOVER PHONE	01750537433	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	Yes
ACCESS KEY HANDED OVER	Yes	SITE TYPE	GFT
BTS TYPE	Outdoor		
SHARED WITH OPERATOR	Yes	SHARED OPERATOR NAME	Robi

GENERATOR INFORMATION


DG BRAND	FG Wilson	GENSET ASSET NO.	N/A
CAPACITY (KVA)	22	TYPE	Can
FUEL TANK CAPACITY	850	PRESENT RH	341.5
FUEL (NO WATER)	163 L	FUEL (TOTAL)	179 L
WATER AMOUNT	16 L	FUEL AMOUNT (WORD)	One Hundred Seventy Nine Liters
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Lucas	BATTERY SERIAL	3AI5VY12787359
BATTERY AH	100	ENGINE SERIAL	HP51109V983311P
ATS BRAND	Local	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-07-31
KEY TYPE	Local Key	KEY STATUS — BTS	00
KEY STATUS — DG ROOM	Open		
ACTIVE DG	1	CONNECTED FUEL TANKS	1

FAULTY/DISCONNECTED DG	0	FAULTY/DISCONNECTED TANKS	0

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	42
Frequency (Hz)	48.8	Phase	3 Phase
Output	401	Engine Brand	Parkingd
Voltage L1-L2	401	Voltage L2-L3	402
Voltage L3-L1	402	Voltage L1-N	230
Voltage L2-N	231	Voltage L3-N	231
Current Line 1	14	Current Line 2	14
Current Line 3	14	N-G	1.86
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	NOK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	OK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		


SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-017	DG	DG - Other	DG fan bet losse	Faulty	—	Open	
S-018	DG	DG - Other	Radiator s blocked with dust.	Faulty	—	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	1) Fan belt loose 2) Rediotor not ciling
SAFETY REMARKS	—
GENERAL REMARKS	PDF checklist notes: DG last servicing date noted 31-7-26. Engine Brand field has original text crossed out and rewritten as illegible 'Perkins' near serial number. Second snag note ('Radiator not ceiling') is ambiguous handwriting - flagged for human review to confirm exact meaning.

SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge



Additional



Additional



Additional



Additional



Additional

Md. Eidris Ali
Handed Over By · Dhaly Infratech
01750537433

Date: _____

Md. Ismail Hossain
Taken Over By · Alliance Computers Limited
01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (39)

Full-size reference photos for SYL_X0086, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)




Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (2)




Photo 4 — S-017 — DG fan bet losse




Photo 5 — S-018 — Radiator s blocked with dust.

ADDITIONAL PHOTOS (34)



Photo 6 — Additional Photos 1




Photo 7 — Additional Photos 2




Photo 8 — Additional Photos 3



Photo 9 — Additional Photos 4



Photo 10 — Additional Photos 5



Photo 11 — Additional Photos 6



Photo 12 — Additional Photos 7




Photo 13 — Additional Photos 8




Photo 14 — Additional Photos 9



Photo 15 — Additional Photos 10




Photo 16 — Additional Photos 11



Photo 17 — Additional Photos 12



Photo 18 — Additional Photos 13



Photo 19 — Additional Photos 14




Photo 20 — Additional Photos 15




Photo 21 — Additional Photos 16



Photo 22 — Additional Photos 17




Photo 23 — Additional Photos 18



Photo 24 — Additional Photos 19



Photo 25 — Additional Photos 20



Photo 26 — Additional Photos 21




Photo 27 — Additional Photos 22



Photo 28 — Additional Photos 23




Photo 29 — Additional Photos 24



Photo 30 — Additional Photos 25



Photo 31 — Additional Photos 26



Photo 32 — Additional Photos 27



Photo 33 — Additional Photos 28



Photo 34 — Additional Photos 29



Photo 35 — Additional Photos 30



Photo 36 — Additional Photos 31



Photo 37 — Additional Photos 32




Photo 38 — Additional Photos 33



Photo 39 — Additional Photos 34