Site HOTO Report — DHK_X1097

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:14 BD time

45%	0/0	0	0	0
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X1097	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Narsingdi
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Hossain	TAKEOVER PERSON	Mosharof
HANDOVER PHONE	01715163812	TAKEOVER PHONE	01781409484
INSPECTED BY	Mosharof	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	FG Wilson	GENSET ASSET NO.	—
CAPACITY (KVA)	30	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	7371
FUEL (NO WATER)	183 L	FUEL (TOTAL)	183 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	—	BATTERY SERIAL	—
BATTERY AH	160	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	Digitized from scanned paper HOTO checklist (Narsingdi zone backfill). NOTE: handover date not legible on original form -- estimated from batch pattern, needs Narsingdi team confirmation. | PDF checklist notes: Site ID header written on the form as 'DHK-1097' (missing the 'X' seen in the filename DHK_X1097) - flagging for human verification this is indeed the same site. Site Address field left entirely blank. DG last servicing date field also left blank. Battery brand/SN field left blank. 'No of active DG / connected fuel tanks / faulty disconnected DG / faulty disconnected tanks' rows all left blank (unlike most other sites in this batch which had 'Active' scrawled in). Checklist for Disconnected generator and spare parts table is empty - no snags recorded. All connected-generator checklist items marked OK. Fuel calc note: Total fuel=(122x122x12.3)=183 liters, matching the 183L entered. Handover Status: 'Completed' has a checkmark. Handing-over vendor name is crossed out/struck through and rewritten as 'Mir Hossain' with phone 01715163312.

SITE PHOTOS

Not Filled Site / Nameplate

Not Filled DG RH / Meter

Not Filled Fuel Gauge

Hossain
Handed Over By · Dhaly Infratech
01715163812

Date: _____

Mosharof
Taken Over By · Alliance Computers Limited
01781409484

Date: _____

BL Concern · Name / Signature

Date: _____