Site HOTO Report — DHK_X1805

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:45 BD time

45%	0/0	1	1	0
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X1805	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Narsingdi
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Hossain	TAKEOVER PERSON	Mosharof
HANDOVER PHONE	01715163812	TAKEOVER PHONE	01781409484
INSPECTED BY	Mosharof	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	—	PRESENT RH	308.6
FUEL (NO WATER)	338 L	FUEL (TOTAL)	380 L
WATER AMOUNT	42 L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Parcking	BATTERY SERIAL	—
BATTERY AH	100	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-027	DG	DG - Controller/Electronics	Controller Sensor	Faulty	DG Controller Box faulty	Open	—

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	Digitized from scanned paper HOTO checklist (Narsingdi zone backfill). NOTE: handover date not legible on original form -- estimated from batch pattern, needs Narsingdi team confirmation. | PDF checklist notes: Top-of-page handwritten note gives fuel calc: Total Fuel=380L, Water=42L, Actual Fuel=338L (formula 94x91x44.5/1000=380L, water found 42L). Site Address: Narshingdi Bazar (approx, handwritten). Most checklist OK/NOK checkboxes ticked OK except DG Controller Box marked faulty in remarks. Engine serial number and DG last servicing date left blank. No of active DG / connected fuel tanks / faulty DG / faulty tanks fields left blank. BL Concern name/signature field blank.

SITE PHOTOS

Not Filled Site / Nameplate

Not Filled DG RH / Meter

Not Filled Fuel Gauge

Md. Hossain
Handed Over By · Dhaly Infratech
01715163812

Date: _____

Mosharof
Taken Over By · Alliance Computers Limited
01781409484

Date: _____

BL Concern · Name / Signature

Date: _____