Site HOTO Report — DHK_X3450

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 08-Nov-2026 03:42 BD time

55%	0/0	2	2	66
FORM COMPLETION	CHECKLIST OK	OPEN SNAGS	TOTAL SNAGS	PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X3450	ZONE	Sylhet
HOTO DATE	2026-09-04	DISTRICT	Kishoreganj
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Sree Bishwajit Kumar
HANDOVER PHONE	01958313020	TAKEOVER PHONE	01850950232
INSPECTED BY	MD KABIR HOSSEN	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	FG Wilson	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	55.0
FUEL (NO WATER)	— L	FUEL (TOTAL)	260 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Spark	BATTERY SERIAL	3J16L11028553
BATTERY AH	Spark (value not legible)	ENGINE SERIAL	FGWPEPOGLPDF2270
ATS BRAND	Navana	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	2025-04-30
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	Active	**CONNECTED FUEL TANKS**	Active
FAULTY/DISCONNECTED DG	Active	**FAULTY/DISCONNECTED TANKS**	Active


SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-129	General	—	DG Room Light	Faulty	Faulty (from paper HOTO checklist PDF, transcribed 2026-09-16)	Open	—
S-130	General	—	DG Canopy	Not Available	1 pc canopy missing (from paper HOTO checklist PDF, transcribed 2026-09-16)	Open	—

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG Room Light Faulty; 1pc DG canopy missing (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X3450_EXTRA_007.jpg) on 2026-09-09. | PDF checklist notes: Site Address: Dori-Chondiben (spelling approximate, handwritten). All checklist rows marked OK. DG last servicing date 30.04.25. Genset Asset No, BL Concern name/signature, and Date of Handover fields left blank.


SITE PHOTOS



Not Filled Site / Nameplate



DG RH / Meter




Not Filled Fuel Gauge



Additional



Additional




Additional



Additional



Additional



Additional

Md. Kabir Hossen
Handed Over By · —
01958313020

Date: _____

Sree Bishwajit Kumar
Taken Over By · —
01850950232

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (66)

Full-size reference photos for DHK_X3450, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)



Photo 1 — DG RH / Meter

ADDITIONAL PHOTOS (65)



Photo 2 — Additional Photos 1




Photo 3 — Additional Photos 2



Photo 4 — Additional Photos 3



Photo 5 — Additional Photos 4



Photo 6 — Additional Photos 5




Photo 7 — Additional Photos 6




Photo 8 — Additional Photos 7



Photo 9 — Additional Photos 8



Photo 10 — Additional Photos 9



Photo 11 — Additional Photos 10



Photo 12 — Additional Photos 11



Photo 13 — Additional Photos 12



Photo 14 — Additional Photos 13



Photo 15 — Additional Photos 14



Photo 16 — Additional Photos 15



Photo 17 — Additional Photos 16



Photo 18 — Additional Photos 17



Photo 19 — Additional Photos 18



Photo 20 — Additional Photos 19



Photo 21 — Additional Photos 20



Photo 22 — Additional Photos 21



Photo 23 — Additional Photos 22




Photo 24 — Additional Photos 23



Photo 25 — Additional Photos 24



Photo 26 — Additional Photos 25



Photo 27 — Additional Photos 26



Photo 28 — Additional Photos 27



Photo 29 — Additional Photos 28




Photo 30 — Additional Photos 29




Photo 31 — Additional Photos 30



Photo 32 — Additional Photos 31



Photo 33 — Additional Photos 32



Photo 34 — Additional Photos 33




Photo 35 — Additional Photos 34



Photo 36 — Additional Photos 35



Photo 37 — Additional Photos 36



Photo 38 — Additional Photos 37



Photo 39 — Additional Photos 38



Photo 40 — Additional Photos 39



Photo 41 — Additional Photos 40




Photo 42 — Additional Photos 41




Photo 43 — Additional Photos 42




Photo 44 — Additional Photos 43



Photo 45 — Additional Photos 44



Photo 46 — Additional Photos 45



Photo 47 — Additional Photos 46



Photo 48 — Additional Photos 47



Photo 49 — Additional Photos 48



Photo 50 — Additional Photos 49



Photo 51 — Additional Photos 50




Photo 52 — Additional Photos 51



Photo 53 — Additional Photos 52



Photo 54 — Additional Photos 53



Photo 55 — Additional Photos 54



Photo 56 — Additional Photos 55




Photo 57 — Additional Photos 56



Photo 58 — Additional Photos 57



Photo 59 — Additional Photos 58



Photo 60 — Additional Photos 59



Photo 61 — Additional Photos 60



Photo 62 — Additional Photos 61



Photo 63 — Additional Photos 62



Photo 64 — Additional Photos 63



Photo 65 — Additional Photos 64



Photo 66 — Additional Photos 65